

HABS
DC,
WASH.
585-A-

HISTORIC AMERICAN BUILDINGS SURVEY

Index to Photographs

Atlantic Building
930 F Street, NW
Washington
District of Columbia

HABS No. DC-569-A

Photographer: John McWilliams, Summer 1990.

DC-569-A-1	FRONT VIEW FROM NORTH
DC-569-A-2	DETAIL OF FRONT ENTRANCE SHOWING FIRST THROUGH FOURTH FLOORS
DC-569-A-3	CLOSE-UP OF ENTRANCE DOORWAY
DC-569-A-4	THREE-QUARTER VIEW FROM SOUTHWEST OF REAR ELEVATION
DC-569-A-5	FIRST FLOOR REAR ROOM, SAFE DEPOSIT ROOM (Note: This was the 9:30 Club during the early 1980s)
DC-569-A-6	FIRST FLOOR REAR ROOM, DETAIL OF CAST IRON COLUMNS
DC-569-A-7	STAIRCASE, LOOKING UP FROM FIRST LANDING
DC-569-A-8	STAIRCASE, LOOKING DOWN FROM SEVENTH FLOOR
DC-569-A-9	ELEVATOR AT SECOND FLOOR
DC-569-A-10	SIXTH FLOOR, FRONT ROOM
DC-569-A-11	EIGHTH FLOOR, ASSEMBLY ROOM
DC-569-A-12	EIGHTH FLOOR, REAR ASSEMBLY ROOM
DC-569-A-13	LOOKING THROUGH BROKEN SKYLIGHT ABOVE THE STAIRWELL TO IRON BEAM (NOTE: BEAM MAY HAVE BEEN USED TO HOIST HEAVY OBJECTS)